TOUGH PROTECTIVE COATING IN **ANY** COLOR

APPLICATION PROCESS BEDLINER



Personal Protective Equipment:

- Air-fed Mask Safety Glasses
 Protective Gloves Disposable Paint Overalls



PRE-TREATMENT

Degrease using U-POL System 20 Solvent Based Degreaser (UP2012) using a pump bottle and wipe using a panel wipe cloth. Remove any rubber grommets, strap anchors and inspection plate from tail gate.



ABRADING SURFACE

Sand the surface with P220 sandpaper on an orbital sander and a red Scotch-Brite finishing pads or nylon fiber cup wheel. Make sure all areas to be coated with RAPTOR are sanded.



PRE-TREATMENT

① 5 mins

Degrease using U-POL System 20 Solvent Based Degreaser (UP2012) using a pump bottle and wipe using a panel wipe cloth.



MASKING

Using masking film, cover the vehicle cutting out areas where RAPTOR will be applied. Apply fine line masking tape on edges to ensure hard clean lines.





PRE-TREATMENT

Degrease using U-POL System 20 Solvent Based Degreaser (UP2012) using a pump bottle and wipe using a panel wipe cloth.





PRIMING - ADHESION PROMOTER

Prime exposed bare metal with two light coats of RAPTOR Acid Etch Primer. Apply 1-2 light coats of RAPTOR Adhesion Promoter to hard to reach areas.





With the air pressure set at 60 PSI (4 Bar), apply two coats of RAPTOR allowing 45-60 minutes flash off between coats.





DRY TIMES

Oven Bake Force Dry: 30 mins @ 140°F. Air Dry: 12 hours @ 68°F. Light Duty Use: 2-3 days. Heavy Duty Use: 7 days.







| Step | | |
|------|--------|--------------------------|
| 735 | UP2012 | Fast Degreaser |
| 2 | UP0413 | Red Finishing Pads |
| 4 | UP5024 | RAPTOR Adhesion Promoter |
| 6 | UP5023 | RAPTOR Acid Etch Primer |

| Step | Part Number | Description |
|------|-------------|--------------------------|
| 2 | UP0820 | Black RAPTOR Kit 4Ltr |
| | UP0821 | Tintable RAPTOR Kit 4Ltr |
| | UP0726 | Application Gun |

